

# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Flexshell Jacket. J617

## Product photo



With supple 4-way stretch for easy mobility, this soft shell jacket flexes and moves, while shielding you from the elements with 5K/5K weather-fighting protection.

- 100% polyester knit bonded to a water-repellent, breathable film insert and 100% polyester fleece lining
- Fabric waterproof rating: 5000MM
- Fabric breathability rating: 5000G/M<sup>2</sup>
- Reverse coil zippers
- Front zippered pockets
- Open hem • Water protection method: Laminate film and durable water-repellent finish (DWR)

### CARE INSTRUCTIONS

Machine Wash Cold Separately Or With Like Colors. Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Cool Iron If Necessary.

## Sketches



front



back

# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Flexshell Jacket. J617

## PRODUCT MEASUREMENTS

|                                | XS     | S      | M      | L      | XL     | 2XL    | 3XL    | 4XL    |
|--------------------------------|--------|--------|--------|--------|--------|--------|--------|--------|
| Body Length at Back            | 25 1/2 | 26 1/2 | 27 1/2 | 28 1/2 | 29 1/2 | 30 1/2 | 31     | 31 1/2 |
| Chest                          | 19     | 20 1/2 | 22     | 23 1/2 | 25     | 26 1/2 | 28 1/2 | 30 1/2 |
| Sleeve Length from Center Back | 33 3/4 | 34 1/2 | 35 1/4 | 36     | 36 3/4 | 37 1/2 | 38 1/4 | 39     |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS


|       | XS    | S     | M     | L     | XL    | 2XL   | 3XL   | 4XL   |
|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 32-34 | 35-37 | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 |

# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Flexshell Jacket. J617

## HOW TO MEASURE



### CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS



Deep Black  
PMS BLACK  
C



Grey Steel  
PMS 7540C



Smoke Grey  
PMS COOL  
GRAY 11C



True Navy  
PMS 533C



True Royal  
PMS 7687C