

SPEC SHEET + MEASUREMENTS



Mercer+Mettle® Short Sleeve UV Capital Tech Shirt. MM2006

Product photo



Redefine your wardrobe with this stretch woven style that combines dress shirt sophistication with the performance of a tech piece. Polished, lightweight and destined to be worn untucked, it is versatile, professional and always fashionable.

Fabric+Weight

- 3.5-ounce, 52/36/12 polyester/recycled polyester/spandex

Features+Benefits

- UPF rating of 30+
- Moisture-wicking
- Stretch
- Easy care
- Open collar with removable collar stays
- Pearlized buttons
- Left chest chevron pocket
- Back yoke with box pleat

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Do Not Use Fabric Softener. Do Not Bleach. Tumble Dry Low. Remove Promptly. Cool Iron If Necessary.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Mercer+Mettle® Short Sleeve UV Capital Tech Shirt. MM2006

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	28	29	30	31	32	33	33 3/4	34 1/2
Chest	18 1/2	20	21 1/2	23	25	27	29 1/2	32 1/2
Sleeve Length from Center Back	17 3/4	18 1/4	18 3/4	19 1/4	19 3/4	20 1/4	20 3/4	21 3/8
Neck Circumference	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4
Chest Pocket Height	5	5	5 1/4	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2
Chest Pocket Width	4 1/2	4 1/2	4 3/4	4 3/4	4 3/4	4 3/4	4 3/4	5

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Chest Pocket Height: Measure from top to bottom at center.

SPEC SHEET + MEASUREMENTS




Mercer+Mettle® Short Sleeve UV Capital Tech Shirt.
MM2006

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.
Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Deep Black
PMS BLACK
C



Deep Black
Triangle Print
PMS BLACK
C



Harbor Blue
PMS 2167C



Night Navy
Dash Print