

SPEC SHEET + MEASUREMENTS

Brooks Brothers

Brooks Brothers® Wrinkle-Free Stretch Pinpoint Spread Collar Shirt. BB18012

Product photo



This iconic dress shirt combines a little bit of stretch with a classic spread collar for a polished look. A premium wrinkle-free treatment process means effortless style and a sharp, professional finish all day long.

- 4.4-ounce, 97/3 cotton/spandex fine yarn count
- Taped seams
- Spread collar with removable stays
- Left chest pocket
- Pearlized buttons
- Rounded, adjustable single-button cuffs

Care Instructions Machine Wash Warm With Like Colors. Only Non-Chlorine Bleach, If Needed. Tumble Dry Low, Remove Promptly And Hang. Warm Iron, If Needed.

Sketches



front



back

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	29 1/2	30	30 1/2	31	31 1/2	32	32 1/2	33
Chest	19 1/2	21	22 1/2	24	26	28	30 1/2	33 1/2
Chest Pocket Height	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Chest Pocket Width	4 1/2	4 1/2	4 3/4	4 3/4	4 3/4	4 3/4	4 3/4	5
Neck Circumference	15 1/2	16	16 3/4	17 1/2	18 1/4	19	19 7/8	20 7/8
Sleeve Length from Center Back	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Chest Pocket Height: Measure from top to bottom at center.


Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2
Chest	32-34	35-37	38-40	41-43	44-47	48-51	52-56	57-61
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS

Cobalt Blue

Deep Black
PMS BLACK C

Newport Blue
PMS 7681C

White
PMS WHITE C